

April 8, 1982



Log No. K82-610
File: RR 2 (NP-33-82-18)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-015
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: March 12, 1982

Enclosed are three copies of Licensee Event Report 82-015 including supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

A handwritten signature in cursive script that reads 'Terry D. Murray'.

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy



8204200259 820408
PDR ADOCK 05000346
S PDR

EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652

APR 14 1982

IE 22
5
11