

LICENSEE EVENT REPORT

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5				
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58			59

CON'T

7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During normal operation at 0830, Reactor Protective System (RPS)
0	3	Channel "B" Hi Power, Thermal Margin/Low Pressure and Axial Shape Index
0	4	Trip Units (TUS) were bypassed due to a TH input failing low
0	5	(T.S. 3.3.1.1). The TUs were returned to service at 1130. The three
0	6	redundant channels remained operable during the event. Similar
0	7	event: None.
0	8	

7 8 9 80

0 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
7	8	I	A	E	X	I	N	S	T	R	U	T	Z				
		9	10	11	12	13	18						19	20			
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8 2		0 0 9		0 3		L		0									
21		22		24		28		30		32							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
Z	Z	Z	Z	Z	Z	0	0	0	0	N	Y	N	R	3	3	5	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 On 3-14-82, prior to troubleshooting, symptoms disappeared. On 3-22-82,

1 1 symptoms reappeared and cause was determined to be temperature transmit-

1 2 ter 1-TT-112HB. Replaced transmitter. Since temperature loop is

1 3 checked on each shift and channel is functionally tested monthly, no

1 4 further corrective action is deemed necessary.

7 8 9 80

FACILITY STATUS (28) 30 OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 E 1 0 0 NA A Operator Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) NA (35)

7 8 9 10 11 44

AMOUNT OF ACTIVITY

NA (36)

LOCATION OF RELEASE

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7		0	0	0	Z			NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40
		NA			

TYPE		DESCRIPTION	
1	9	Z NA	(43)

2 0 N 44 NA S PDR
 PUBLICITY
 ISSUED DESCRIPTION (45)
 8204220196 820412
 PDR ADOCK 05000317
 NRC USE ONLY

NAME OF PREPARER G.S. Pavis/J.W. Raynor

PHONE: 301-269-4742/4713