



ARKANSAS POWER & LIGHT COMPANY

Arkansas Nuclear One
P.O. Box 608
Russellville, AR 72801

April 16, 1982

ANO-82-2805

Mr. John Collins
Regional Administrator
Office of Inspection and Enforcement
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

SUBJECT: LER 50-368/82-011

Gentlemen:

This letter confirms the conversation between Mr. W. D. Johnson (ANO Resident NRC Inspector) and Mr. J. P. O'Hanlon (ANO General Manager) at 0947 hours on April 16, 1982. In this conversation, Mr. O'Hanlon notified Mr. Johnson of a potentially reportable item under Tech Spec 6.9.1.8.C.

At 1415 hours on April 15, 1982, a leak was discovered inside containment in the "B" steam generator blow down line between valve 2CV1065 and the containment penetration. This occurrence caused entry into the action statement of Tech Spec 3.6.1.1. The outside containment isolation valve (2CV1066-1) was promptly closed to assure containment integrity. The unit was operating at full power at the time of discovery.

The unit is presently shutdown. The steam generator blow down line will be repaired prior to startup. Further details will follow in Licensee Event Report (LER) 40-368/82-011.

Sincerely yours,

James P. O'Hanlon

James P. O'Hanlon
General Manager
Arkansas Nuclear One


8204280 450

JPO:man

S

cc: W. Cavanaugh, III
J. M. Griffin
J. R. Marshall
INPO
Resident NRC Inspectors

MEMBER MIDDLE SOUTH UTILITIES SYSTEM



IE-92
5-92
1/0