

Report No. 82-10/01x-0

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	8	0	5	0	-	0	2	7	7	7	0	4	1	3	8	2	0	5	1	3	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

0 2 Eberline Instrument Corporation reported a 9.175 Rem exposure to TLD badge processed for the month of March. Eberline also reported that badge was coded for February and label was affixed upside down.

0 3

0 4

0 5 Investigation revealed that an individual's badge had been switched by a co-worker with a badge that had been found under a pipe which transfers liquid rad waste. Review of RWP's and Harshaw badge readings led to conclusion that no individual actually received an overexposure.

0 6

0 7

0 8

09		SYSTEM CODE ZZ		11	CAUSE CODE A		12	CAUSE SUBCODE X		13	COMPONENT CODE ZZZZZZ						14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		16			
7	8	9	10		11		12		13						18		19		20							
17		LER/NO REPORT NUMBER		EVENT YEAR 82		21	22	SEQUENTIAL REPORT NO. 010		24	26	OCCURRENCE CODE 01		28	29	REPORT TYPE X		30	REVISION NO. 0		32					
ACTION TAKEN H		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0000		22	ATTACHMENT SUBMITTED Y		23	NPRD-4 FORM SUB. N		24	PRIME COMP. SUPPLIER Z		25	COMPONENT MANUFACTURER Z999		26
33	34		35		36		37		38		39	40		41		42		43		44		45		46	47	

1 0 Cause of event was deliberate tampering with a badge after it was found
1 1 near a radiation source. The individual who found the badge switched it
1 2 with a co-worker's badge without his knowledge. This individual has
1 3 been permanently denied access to the site.

1	4											80				
7	8	9											80			
FACILITY STATUS			% POWER			OTHER STATUS (30)			METHOD OF DISCOVERY				DISCOVERY DESCRIPTION (32)			
1	5	H (28)	0	0	0 (29)	U/3 Full Power			D (31)	Notification from vendor						
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY (35)			LOCATION OF RELEASE (36)							
1	6	Z (33)	Z (34)	N/A			N/A									
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION (39)							
1	7	0	0	0 (37)	Z (38)	N/A										
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
PERSONNEL INJURIES			NUMBER			DESCRIPTION (41)										
1	8	0	0	0 (40)	N/A											
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION (43)										
1	9	Z (42)	N/A													
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
PUBLICITY			ISSUED			DESCRIPTION (45)										
2	0	N (44)	N/A History													
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
8206110021 820601													NRC USE ONLY			

8206110021 820601
PDR ADCK 05000277
S PDR

M. J. Cooney

PHONE: (215) 841-5020