



C. 7-10 7

Federal Emergency Management Agency

Region VIII Denver Federal Center, Building 710 Denver, CO 80225

June 9, 1982

Mr. John T. Collins
Regional Administrator
USNRC, Region IV
Arlington, Texas 76011

Dear Mr. Collins:

The attached letter from Mr. Robert Heggie, RAC member and Emergency Coordinator for the Department of Health & Human Services, addresses one issue in connection with the test of the Fort St. Vrain prompt notification system.

Mr. Heggie informs me that there will be additional data available as a result of the over-all evaluation of the "tone-alert" system. When this information is available I will provide you the data. The attached test data represents 280 door-to-door visits with 99 of the 280 not at home for one reason or another.

I want to thank you for providing the timely assistance of Mr. Jim Montgomery. His membership on three Regional Assistance Committees makes his expertise extremely valuable. During the "after action" critique of the exercise Jim provided the Region VIII RAC members an insight on the "workings" of other Region RAC activities during exercises. This information will help the Region VIII RAC in its future deliberations.

Sincerely,

N. Paul Alley

N. Paul Alley, Chairman
Regional Assistance Committee

RECEIVED

JUN 14 1982


June 7, 1982

Mr. Paul Alley
Federal Emergency Mngmt. Agency
Denver Federal Center
Building 710
Denver, Colorado 81225

Dear Paul:

During our June 3, 1982 survey of the Fort St. Vrain Exercise, the following sites indicated that they did not have a radio receiver or had other problems. This information is being provided to you for dissemination to the appropriate PSC and/or state official.

<u>NAME</u>	<u>ADDRESS</u>	<u>PROBLEM</u>
Loretta Mock	603 Olive Way	Receiver left at last residence, called for replacement but no results.
Leon Beglow	304 Olive Lane	Has problems with receiver, PSC called but response was no good.
Plattville Hardware	600 Main Street	Set does not work.
M. Camp	1200 Division	Set does not operate at all.
Linda Redrick	14975 County Rd. 21	Set does not work on batteries.
77	1501 Balle Vista	Set does not work.
Richard Evis	13690 County Road 17	Does not have receiver, just moved in.
Norgren (Big House)	County Road 30 1/2 & 23	Does not work.
Asmassen	8567 County Road 30	Does not work well.
Rick Apple	14533 Road 19	Just moved in, does not have receiver.
Richard Smith	16202 Road 15	Did not go off may be a problem




FBI REGION VIII
INSURANCE & MITIGATION

Page 1 - Mr. Paul Alley
June 7, 1981

<u>NAME</u>	<u>ADDRESS</u>	<u>PROBLEM</u>
Johnson	County Rd. 19 @ RR Track	Reception poor, garbled.
Ellis	County Road 15	Does not have radio.
Yates	7790 County Road 42 @ 17	Does not have radio.
Smith	16202 County Road 15	Tone does not go off. Can push button to get weather information.

Please provide information on the disposition of this matter. Thank you in advance for your expeditious assistance.

Sincerely yours,



Robert F. Heggie
Emergency Coordinator