

MADEY COSSEY  
WEST RUMNEY VILLAGE  
RUMNEY NH 03266

western union

Mailgram®



4-0178418186 07/05/82 ICS IPMBNGZ CSP WSHB  
6037869278 MGM TDBN RUMNEY NH 207 07-05 1119P EST

U.S. NUCLEAR REGULATORY COMMISSION  
ATTN DIRECTOR  
TECHNICAL INFORMATION AND DOCUMENT CONTROL  
WASHINGTON DC 20555

PLEASE ENTER MY FOLLOWING COMMENT ON NUREG-0895, ENVIRONMENTAL  
STATEMENT ON SEABROOK NUCLEAR PLANT:

(1) SEABROOK'S OWNER/BUILDER, PSNH, DOES NOT CONSIDER ITS SEACOAST  
SITE SUFFICIENTLY "SAFE" FROM MAJOR EARTHQUAKES OR IT WOULD HAVE MADE  
OR ATTEMPTED TO MAKE ITS COOLING TUNNEL SYSTEM "EARTHQUAKE PROOF."  
RATHER, IT IS BUILDING ON-SITE, A SINGLE COOLING TOWER TO BE SHARED  
BY BOTH NUCLEAR UNITS IN THE EVENT OF A HIGH-MAGNITUDE EARTHQUAKE  
RENDERING ITS COOLING TUNNELS UNUSABLE. HOW CAN PSNH'S LACK OF  
CONFIDENCE IN ITS SITE BE RECONCILED WITH AN E.S. WHICH ESSENTIALLY  
SAYS THE SITE IS FINE?

(2) IN EARLY SPRING OF 1980, WORKERS AT SEABROOK NUCLEAR PLANT WERE  
FOUND TO BE DOING CONSTRUCTION WORK WHILE UNDER THE INFLUENCE OF  
DRUGS. OUR NEW HAMPSHIRE GOVERNOR GALLEN REQUESTED THE NRC TO DO A  
STUDY OF THE QUALITY OF CONSTRUCTION DONE DURING THE DRUG-TAKING  
TIME. I HAVE ASKED THROUGH THIS SPRING, 1982, FOR A COPY OF THAT  
STUDY AND THEN TOLD IT IS NON-EXISTENT. HOW CAN THE NRC SAY THE  
SEABROOK PLANT WILL NOT EVER HAVE A DETRIMENTAL EFFECT ON THE  
ENVIRONMENT WHEN THE QUALITY OF THE CONSTRUCTION WORK IS NOT ASSURED?

LYNN RUDMIN CHONG, WEST RUMNEY VILLAGE, RUMNEY NH 03266

23:21 EST

MGMCOMP

COO2B

8207080112 820705  
PDR ADOCK 05000443  
D PDR



**Mailgram®**



MAILGRAM POSTAL  
CHARGES PAID

THIS MAILGRAM WAS TRANSMITTED ELECTRONICALLY BY WESTERN UNION TO A POST OFFICE NEAR YOU FOR DELIVERY