

USNRC
ATLANTA
DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

82
JUL 12 AG 31
July 6, 1982

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-48 was to have been submitted by July 5, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.4.5, "All power operated relief valves (PORVs) and their associated block valves shall be operable"; and T.S.3.3.3.6, "The accident monitoring instrumentation channels shown in Table 3.3-10 shall be operable", which were violated on June 5, 1982. At this time, investigation of the incident has not been completed. The report will be submitted by July 16, 1982.

Very truly yours,


William O. Parker, Jr.

PBN/jfw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

OFFICIAL COPY

8207150129 820706
PDR ADOCK 05000369
S PDR

EE22