



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 16, 1982  
RBG-13,032  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-60


On June 15, 1982, Gulf States Utilities Company (GSU) notified the Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the installation of non-seismic pipe supports over Category I components in the Control Building at River Bend Station (DR-60). GSU has not completed its investigation at this time. An interim or final status report will be submitted by September 2, 1982.

Sincerely,

*for* J. E. Booker  
Manager-Engineering & Licensing  
River Bend Nuclear Group

JEB/*ERK*/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555



8207230108 820716  
PDR ADUCK 05000458  
S PDR