



## Nebraska Public Power District

COOPER NUCLEAR STATION  
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321  
TELEPHONE (402) 825-3811

CNSS907353  
August 2, 1990

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Reference 1: ASME Section XI, 1980 Edition, Winter 1981 Addenda, Article  
IWA-6000.

Subject: Section XI Code Reports  
Cooper Nuclear Station  
NRC Docket No. 50-298, DPR-46

Gentlemen:

Pursuant to the reporting requirements of Reference 1, the subject code reports are submitted as enclosures to this letter for review by your office.

Enclosure 1, "Owner's Data Report for Inservice Inspections" (Form NIS-1), documents Inservice Inspection activities conducted at Cooper Nuclear Station during refueling outage number thirteen (Spring 1990 Refueling Outage). Enclosure 2, "Owner's Report for Repairs and Replacements" (Form NIS-2), documents repair and replacement activities conducted at Cooper Nuclear Station during operating cycle number thirteen and refueling outage number thirteen.

Please contact J. R. Flaherty, Engineering Manager at Cooper Nuclear Station, if you should require additional information regarding this matter.

Sincerely,



G. K. Trevors

Senior Staff Advisor to the  
Nuclear Power Group

GAT:RAS:sa

Enclosures

cc: NRC Regional Office  
Region IV  
Arlington, Texas

W. R. Bennett  
NRC Resident Inspector  
Cooper Nuclear Station

9008090189 900802  
FDR ADOCK 05000298  
Q PDC

A047  
111