



Duke Power Company  
McGuire Nuclear Generation Department  
12700 Hagers Ferry Road (MG01A)  
Huntersville, NC 28078-8985

T. C. McMEEKIN  
Vice President  
(704)875-4800  
(704)875-4809 FAX



DUKE POWER

September 6, 1993

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: **McGuire Nuclear Station, Unit 2**  
**Docket No: 50-370**


Dear Sir:

Attached is Revision 1 to the McGuire Unit 2 Leak Investigation and Report that described investigation and actions that were taken and are planned as a result of the steam leak through Unit 2 "A" steam generator secondary side drain line.

The revision contains the following:

1. A Table of Contents that is to be placed behind the September 5, 1993, transmittal letter.
2. Page 1 to the Sequence of Events that was omitted in Revision 0
3. A Causal Factors Chart which is placed in the Investigative Efforts tab, Section III, Safety Review Group LER
4. A revision to Corrective Actions; Section IV, Control of Plant During Cooldown, Problem Statement 1, Short Term Action Items A
5. A new page 1 Appendix II
6. A revision to the attachment for Appendix II, issues number 1b and 1c; letter dated September 4, 1993, from David Motes to Bruce Travis, page 1
7. A revision to Appendix V; letter dated September 3, 1993, from Ronnie B. White, Jr. to Memorandum to File.

Very truly yours,

  
T. C. McMeekin

A017

⊕

McGuire Nuclear Station, Unit 2  
Docket No: 50-370  
Page 2

xc: Mr. S.D. Ebner  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, Ga. 30323

Mr. Victor Nerses  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. G.F. Maxwell  
NRC Resident Inspector  
McGuire Nuclear Station  
U. S. Nuclear Regulatory Commission