

ATTACHMENT 2

PEACH BOTTOM ATOMIC POWER STATION
UNITS 2 AND 3

Docket Nos. 50-277
50-278

License Nos. DPR-44
DPR-56

ENVIRONMENTAL TECHNICAL SPECIFICATION CHANGES

List of Attached Pages

<u>Unit 2</u>	<u>Unit 3</u>
ii	ii
42	42
48	48
49	49
50	50
53	53

PBAPS

	Page <u>No.</u>
7.2 Action to be Taken if a Protection Limit or Report Limit is Exceeded or if Harmful Effects Detected	49
7.3 Unit Operating Procedures (Deleted)	50
7.4 Plant Reporting Requirements	51
7.4.1 Routine Reports	51
7.4.2 Non-Routine Reports	51
7.5 Records Retention	52
7.5.1 Records Retained for 5 Years	52
7.5.2 Records Retained for the Life of the Plant	52

PBAPS

-LEFT BLANK INTENTIONALLY-

PBAPS

7.0 Administrative Controls

7.1 Organization, Review and Audit

7.1.1 Organization

- A. The Plant Manager is responsible for the operation of the facility and to assure that the facility operates within the limits set forth in the environmental technical specifications.
- B. In all matters pertaining to operation of the facility and to the environmental technical specifications, the Plant Manager shall report to, and consult with the Vice President-PBAPS.

7.1.2 Review and Audit

Committees for review and audit of plant operation are described in Section 6.5 of Appendix A to the Operating License.

PBAPS

- 7.2 Action to be Taken if a Protective Limit or Report Level is Exceeded or if Harmful Effects Detected
- 7.2.1 For the purpose of this specification, an environmental deviation shall be considered as defined in Section 1.0.
- 7.2.2 An environmental deviation shall be reported immediately to the Plant Manager or, in his absence, the Vice President - PBAPS, and promptly reviewed by the Plant Operations Review Committee. This Committee shall prepare a separate report for each environmental deviation. This report shall include an evaluation of the cause of the deviation, the extent and magnitude of the impact, and recommendations for appropriate action to prevent or reduce the probability of such a deviation.

PBAPS

7.2.3

Copies of all such reports shall be submitted to the Vice President - PBAPS, and to the Chairman of the Nuclear Review Board for review and approval of any recommendations.

7.2.4

The Vice President - PBAPS shall report the circumstances of any environmental deviation to the NRC as specified in Section 7.4.2.

7.2.5

If harmful effects or evidence of irreversible damage not considered in the Final Environmental Statement are detected by the monitoring programs, the licensees will provide to the staff an analysis of the problem and a plan of action to be taken to eliminate or significantly reduce the detrimental effects or damage.

7.3 Unit Operating Procedures - Deleted

PBAPS

-LEFT BLANK INTENTIONALLY-

PBAPS

	Page <u>No.</u>
7.2 Action to be Taken if a Protection Limit or Report Limit is Exceeded or if Harmful Effects Detected	49
7.3 Unit Operating Procedures (Deleted)	50
7.4 Plant Reporting Requirements	51
7.4.1 Routine Reports	51
7.4.2 Non-Routine Reports	51
7.5 Records Retention	52
7.5.1 Records Retained for 5 Years	52
7.5.2 Records Retained for the Life of the Plant	52

PBAPS

-LEFT BLANK INTENTIONALLY-

PBAPS

7.0 Administrative Controls

7.1 Organization, Review and Audit

7.1.1 Organization

- A. The Plant Manager is responsible for the operation of the facility and to assure that the facility operates within the limits set forth in the environmental technical specifications.
- B. In all matters pertaining to operation of the facility and to the environmental technical specifications, the Plant Manager shall report to, and consult with the Vice President-PBAPS.

7.1.2 Review and Audit

Committees for review and audit of plant operation are described in Section 6.5 of Appendix A to the Operating License.

PBAPS

- 7.2 Action to be Taken if a Protective Limit or Report Level is Exceeded or if Harmful Effects Detected
- 7.2.1 For the purpose of this specification, an environmental deviation shall be considered as defined in Section 1.0.
- 7.2.2 An environmental deviation shall be reported immediately to the Plant Manager or, in his absence, the Vice President - PEAPS, and promptly reviewed by the Plant Operations Review Committee. This Committee shall prepare a separate report for each environmental deviation. This report shall include an evaluation of the cause of the deviation, the extent and magnitude of the impact, and recommendations for appropriate action to prevent or reduce the probability of such a deviation.

PBAPS

7.2.3

Copies of all such reports shall be submitted to the Vice President - PBAPS, and to the Chairman of the Nuclear Review Board for review and approval of any recommendations.

7.2.4

The Vice President - PBAPS shall report the circumstances of any environmental deviation to the NRC as specified in Section 7.4.2.

7.2.5

If harmful effects or evidence of irreversible damage not considered in the Final Environmental Statement are detected by the monitoring programs, the licensees will provide to the staff an analysis of the problem and a plan of action to be taken to eliminate or significantly reduce the detrimental effects or damage.

7.3 Unit Operating Procedures - Deleted

PBAPS

-LEFT BLANK INTENTIONALLY-