

Georgia Power Company
40 Inverness Center Parkway
Post Office Box 1295
Birmingham, Alabama 35201
Telephone 205 877-7122

C. K. McCoy
Vice President, Nuclear
Vogtle Project



LCV-0179

October 14, 1993

Docket No. 50-425

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555


Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT
SPECIAL REPORT
STEAM GENERATOR TUBES PLUGGED
DURING THIRD UNIT 2 REFUELING OUTAGE

In accordance with the requirements of the Vogtle Electric Generating Plant Unit 1 and 2 Technical Specifications, sections 4.4.5.5.a and 6.8.2, Georgia Power Company hereby submits this special report related to the number of steam generator tubes plugged during the Unit 2 third refueling outage (2R3).

After completion of inservice inspection (ISI) on October 2, 1993, two (2) tubes in steam generator No. 1 that had been previously plugged with Inconel 600 plugs were replugged with Inconel 690 plugs. This reflects our implementation of a previously stated commitment. Complete ISI results will be submitted within 12 months per Technical Specification 4.4.5.5.b.

Sincerely,


C. K. McCoy

CKM/NJS

180060

9310190094 931014
PDR ADDCK 05000425
G PDR

*Acc
1/0*

xc: Georgia Power Company
Mr. J. B. Beasley, Jr.
Mr. M. Sheibani
NORMS

U. S. Nuclear Regulatory Commission
Mr. S. D. Ebnetter, Regional Administrator
Mr. D. S. Hood, Licensing Project Manager, NRR
Mr. B. R. Bonser, Senior Resident Inspector, Vogtle