

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	57 CAT 58			

CON'T

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0655 hours, June 18, 1982, during routine surveillance, it was discovered that the

0 3 | 100' Elevation Containment Air Lock seal leakage was greater than required by the

0 4 | Technical Specifications. The air lock was declared inoperable, and Action Statement

0 5 | 3.6.1.3.a was entered. The outer door was operable and maintained closed to provide

0 6 | containment integrity. This occurrence constituted operation in a degraded mode in

0 7 | accordance with Technical Specification 6.9.1.9.b. (82-047, 82-045, 82-044, 82-023,

0 8 | 82-021)

7 8 9

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		S	A	A	X	P	E	N	E	T	R	A	Z		
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34				
8	2		0	5	1	/	0	3	L		0				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED					
35	36	37	38	39	40	41	42	43	44	45	46				
E	H	Z	Z	0	0	0	0	Y	N	A	C				
18	19	20	21	22	23	24	25	26	27	28	29				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The excessive leakage was due to an improperly positioned seal. Personnel slamming
1 1 the door had caused the seal to be forced into the seal groove. The seal was re-
1 2 positioned, and the door satisfactorily tested. The air lock was declared operable,
1 3 and at 1140 hours, June 18, 1982, the action statement was terminated. Proper door
1 4 operation will be emphasized in training and with caution signs on the air lock doors.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	E	28	1	00	29	NA	B	31	Surveillance Testing	32

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 2 34 NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7		000	37	Z	38	NA		

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	H	0 0 0	NA

11		12		80	
LOSS OF OR DAMAGE TO FACILITY					
TYPE		DESCRIPTION			
1	9	2	42	NA	

80
 PUBLICITY
 ISSUED DESCRIPTION (45) 8207260260 820714
 2 0 N (44) NA PDR ADOCK 05000311
 7 8 9 10 S PDR
 NRC USE ONLY
 68 69 80

NAME OF PREPARER R. Frahm

PHONE: (609) 541-5900 629