



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

August 4, 1982

NORRIS L. STAMPLEY  
SENIOR VICE PRESIDENT

Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Recording of Radgas Effluent  
Sampler Flow Rates  
Reference: LER-82-012/01 T-0  
AECM-82/449

On July 22, 1982, a procedural inadequacy was discovered in the Daily Operating Log. Radioactive gaseous effluent sampler flow rates were not being recorded daily as required by Technical Specifications. Attached is LER 82-012/01 T-0 with supplementary information.

Yours truly,

NLS:lm  
Attachment

cc: Mr. R. B. McGehee (w/o)  
Mr. T. B. Conner (w/o)  
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Document Control Desk (w/a)  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8208090169 820804  
PDR ADOCK 05000416  
S PDR  
AE1N4

OFFICIAL COPY

IE 22