

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5														
7	8	9	14						15	25						26	30						57	CAT	58																		
LICENSEE CODE																												LICENSE NUMBER						LICENSE TYPE									

CON'T

0	1	L	6	0	5	0	0	0	3	6	4	7	1	1	2	4	8	2	8	1	2	2	3	8	2	9
7	8	60				61	DOCKET NUMBER				68	69	EVENT DATE				74	75	REPORT DATE				80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

① At 2000 on 11-24-82, during surveillance test review, it was determined that FNP-2-  
② STP-63.0 (Area Temperature Monitoring) had not been performed within the required  
③ Tech. Spec. time interval. Tech. Spec. 4.7.13 requires that the surveillance be per-  
④ formed daily. The surveillance had been last completed at 1812 on 11-22-82. Tech.  
⑤ Spec. 4.7.13 action statement requirements were met. Health/safety of the public was  
⑥ affected.

0	8																											80
7	8	9																										

0	9	A	A	11	A	12	B	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	8	2	17	0	4	7	18	0	3	19	L	20	0	21	0	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47									
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

① This event was attributed to personnel error. FNP-2-STP-1.0 (Operations Daily and  
② Shift Surveillance Requirements), which schedules daily operations surveillance test-  
③ ing, has been revised to include the performance of FNP-2-STP-63.0. FNP-2-STP-63.0  
④ was satisfactorily completed at 2115 on 11-24-82.

1	4																											80
7	8	9																										

1	5	G	28	0	0	0	29	NA	30	31	Surveillance Test Review																32													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																																

1	6	Z	33	Z	34	NA	35	NA	36	LOCATION OF RELEASE																36														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																																		

1	7	0	0	0	37	Z	38	NA	39																	40														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION																																		

1	8	0	0	0	40	NA	41																	42																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
PERSONNEL INJURIES		NUMBER		DESCRIPTION																																				

1	9	Z	42	NA	43																	44																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																																				

2	0	N	44	NA	45																	46																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
PUBLICATION		ISSUED		DESCRIPTION																																				

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156