

LICENSEE EVENT REPORT

<u>/0/1/</u>	<u>/V/A/N/A/S/2/</u> (2)	<u>/0/0/-/0/0/0/0/0/-/0/0/</u> (3)	<u>/4/1/1/1/1/</u> (4)	<u>/ / /</u> (5)
LICENSEE CODE	LICENSE NUMBER	LICENSE TYPE	CAT	

REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/9/ (7) /1/2/1/3/8/2/ (8) /1/2/2/2/8/2/ (9)

DOCKET NUMBER EVENT DATE REPORT DATE

/0/2/ / On December 13, 1982, with Unit 2 at 100% power, Fire Door S71-18 between the /
 /0/3/ / "2H" Emergency Diesel Generator Room and the Turbine Building would not latch and/
 /0/4/ / lock. Since a fire watch was immediately posted the public health and safety /
 /0/5/ / were not affected. This event is contrary to T.S. 3.7.15 and reportable to /
 /0/6/ / T.S. 6.9.1.9.b. Degradation of fire doors between the Emergency Diesel Room and /
 /0/7/ / the Turbine Building is a recurring event due to the differential pressure during/
 /0/8/ / diesel operation.

SYSTEM		CAUSE		CAUSE		COMP.		VALVE	
CODE		CODE		SUBCODE		SUBCODE		SUBCODE	
<u>/0/9/</u>	<u>/A/B/</u> (11)	<u>/E/</u> (12)	<u>/B/</u> (13)	<u>/X/X/X/X/X/X/X/</u> (14)	<u>/Z/</u> (15)		<u>/Z/</u> (16)		
			SEQUENTIAL		OCCURRENCE		REPORT		REVISION
(17)	LER/RO	EVENT YEAR	REPORT NO.		CODE		TYPE		NO.
	NUMBER	<u>/8/2/</u>	<u>/-/</u> <u>/0/8/2/</u>	<u>/-/</u>	<u>/0/3/</u>		<u>/L/</u>	<u>/-/</u>	<u>/0/</u>

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
<u>/E/</u> (18) (26)	<u>/X/</u> (19)	<u>/Z/</u> (20)	<u>/Z/</u> (21)	<u>/0/0/0/0/</u> (22)	<u>/N/</u> (23)	<u>/N/</u> (24)	<u>/A/</u> (25)	<u>/C/1/7/5/</u>

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / Fire Door S71-18 would not latch because the latch was sticking. The latch was /
/1/1/ / adjusted, lubricated and the operability of the fire door verified. Design /
/1/2/ / modifications to the fire doors between the Emergency Diesel Room and the Turbine /
/1/3/ / Building are being pursued. /
/1/4/ /

FACILITY			METHOD OF		DISCOVERY DESCRIPTION (32)
STATUS	%POWER	OTHER STATUS	DISCOVERY		
<u>/1/5/</u>	<u>/E/ (28)</u>	<u>/1/0/0/ (29)</u>	<u>/ NA / (30)</u>	<u>/A/ (31)</u>	<u>/ Operator Observation /</u>

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
<u>1/16/</u>	<u>1/21</u> (33)	<u>1/21</u> (34)	<u>NA</u>
		<u>NA</u>	<u>NA</u>

PERSONNEL EXPOSURES		
NUMBER	TYPE	DESCRIPTION (39)
<u>/1/7/</u>	<u>/0/0/0/</u> (37) <u>/Z/</u> (38)	<u>/</u> NA

PERSONNEL INJURIES		
NUMBER	DESCRIPTION (41)	
/1/8/	/0/0/0/ (40)	/ NA

LOSS OF OR DAMAGE TO FACILITY (43)		
TYPE	DESCRIPTION	
/1/9/	/Z/ (42)	/ NA

PUBLICITY					
ISSUED	DESCRIPTION (45)	NRC USE ONLY			
/2/0/	/N/ (44) / NA	/	/	/	/

8212300291 821222 NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151
PDR ADOCK 05000339
S PDR

8212300291 821222 NAME
PDR ADCK 05000339
S PDR