



Carolina Power & Light Company

P. O. Box 101, New Hill, N. C. 27562
December 23, 1982

50-400

.RC-31

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 3100)
Atlanta, Georgia 30303

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1985-89 - 900,000 KW - UNITS 1 & 2
WELDING DEFICIENCIES IN THE REACTOR COOLANT PUMP MOTOR
FRAME, WESTINGHOUSE SHOP ORDER 125, ITEM 108

Dear Mr. O'Reilly:

On December 2, 1982, Mr. C. Hehl of the NRC was notified of a potentially reportable item per the provisions of 10CFR50.55(e) and 10CFR, Part 21. The reactor coolant pump motor frames from the vendor (Westinghouse) contained weld deficiencies.

At the present time, Westinghouse is still evaluating the welding on their frames and do not expect to be complete with this until the first part of March, 1983. For this reason, we would request an extension until March 11, 1983 for submitting a report on the reportability of this item.

Thank you for your consideration in this matter.

Yours very truly,

R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/sh

cc: Mr. G. Maxwell (NRC-SHNPP)
Mr. V. Stello (NRC)

OFFICIAL COPY

IE 27