

LICENSEE EVENT REPORT

CONTROL BLOCK:

						①
--	--	--	--	--	--	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	0	1	8	9	C	A	S	O	S	2	14	2	15	0	0	-	0	0	0	0	0	-	0	0	25	3	26	4	1	1	1	1	30	4	32	CAT	58	5
				LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE														

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 6 2 7 1 1 2 8 8 2 8 1 2 1 3 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With the plant in Mode 6 Emergency Chiller E-335 was declared inoperable. This
0 3 rendered CREACUS Train B inoperable. Since Train A was down for charcoal filter
0 4 replacement, LCO 3.7.5 was thus exceeded and LCO 3.0.3 became governing for both
0 5 units. No event requiring CREACUS operation during this period occurred, thus
0 6 public health and safety were not affected.
0 7

7 8 9

0	9		S	G	11	D	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16				
7	8		9	10		11		12		13					18		19		20					
LER/RO REPORT NUMBER		EVENT YEAR				SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE				REVISION NO.								
17		8	2								0	1		T			0							
		21	22			23		24	26	27		28	29		30		31							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER								
G	18	X	19		Z		Z	21	0	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	26
33		34		35		36			37				40	41		42		43		44				47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by the failure of a Resistance Temperature Detector (RTD)

11 in the motor winding high temperature trip circuit. Corrective measures taken included

12 a temporary modification and clearing of the trip. Also; an installed spare RTD

13 will be used in the trip circuit as permanent corrective action.

1 4

7 8 9

FACILITY STATUS: 1 5 8 28
 % POWER: 0 0 0 29
 OTHER STATUS: NA 30
 METHOD OF DISCOVERY: A 31
 DISCOVERY DESCRIPTION: Operator Observation 32

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7		37	2	38	NA	39		

PERSONNEL INJURIES										
NUMBER			DESCRIPTION							
1	2		0	0	0	40	NA			

		LOSS OF OR DAMAGE TO FACILITY			
TYPE		DESCRIPTION		(43)	
1	9	Z	(42) NA	8301030070 821213 PDR ADOCK 05000361 S PDR	

2 0 N 44 NA

NAME OF PREPARED

H. B. Ray

HIB Pkg / TV Monday

PHOTO

714/492-7700

NRC USE ONLY

0-800-4-A-READ