

Colt Industries



50-334
**Fairbanks Morse
Engine Division**
701 Lawton Avenue
Beloit, Wisconsin 53511
608/364-4411

February 15, 1983

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Ill. 60137

Attention: Mr. James G. Keppler, Director, Region III

Subject: Colt Industries-Fairbanks Morse Engine Division
Emergency Diesel Generators
Possible Thermostatic Valve Malfunction
Fail Safe To "Full Cooling Position"
Part 21 Report
Supplemental Report No. 4 - Public Service
Electric & Gas Co.-Hope Creek Unit #1

References: May 25, 1982; June 28, 1982 and September 17, 1982 Part 21
Reports - Robertshaw Valves - same subject


Gentlemen:

The lower overrun assemblies in the Robertshaw valves installed on the Diesel Generator Sets at the Public Service Electric & Gas Co., Hope Creek Unit 1 have been replaced with overrun assemblies utilizing cotter pins to positively lock the nut to the stem.

The units are now free of the reported potential defect.

A copy of this report is being forwarded to the utility involved.

Very truly yours,


J. M. Moriarty
MANAGER UTILITY SALES

JMM:jc

cc: Bechtel Power Corp.
P. O. Box 3965
San Francisco, CA 94119
Attention: Hope Creek Project Engineer

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

Robertshaw Controls Company
P. O. Box 400
Knoxville, TN 37901
Attention: T. T. Howell, Quality Mgr.

A division of the Colt Industries Operating Corp.

8302250201 830215
PDR ADOCK 05000354
S PDR

FEB 18 1983

IE19