

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J O C P I 2 0 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T
01 REPORT SOURCE L G 0 5 0 0 0 0 2 1 1 9 7 0 1 1 1 8 8 3 8 0 2 1 1 5 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During maintenance on 'A' CRD pump, a pump vent line was broken off.
03 Wetdown of core spray pump NZOIA and an inadvertant trip of 'B' CRD pump
04 resulted. As 'B' CRD pump was immediately restarted, and the redundant
05 core spray system and core spray pump in the affected system were opera-
06 ble, the safety significance is minimal. Operation in degraded mode
07 was permitted by Tech. Specs. 3.4.A.4 and 3.4.D.2. This event is reporta-
08 ble per Tech. Spec. 6.9.2.b.2.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

09 SYSTEM CODE CAUSE CODE C-USE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
R B 11 A 12 C 13 P I P E X X 14 A 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 LER/RO REPORT NUMBER 8 3 21 22
18 ACTION TAKEN A 18 33
19 FUTURE ACTION F 19 34
20 EFFECT ON PLANT Z 20 35
21 SHUTDOWN METHOD Z 21 36
22 HOURS 0 0 0 0 37 38 39 40
23 ATTACHMENT SUBMITTED Y 23 41
24 NPD-4 FORM SUB N 24 42
25 PRIME COMP. SUPPLIER Z 25 43
26 REVISION NO. 0 32
27 COMPONENT MANUFACTURER X 9 9 9 9 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 While torquing 'A' CRD pump casing bolts, a pump vent line was broken.
11 Core spray pump NZOIA was wetdown and 'B' CRD pump was inadvertantly
12 tripped. 'B' CRD pump was immediately restarted. Core spray pump NZOIA
13 was removed from service and the motor was tested for water damage.
14 Core spray pump wetdown protection will be evaluated.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

15 FACILITY STATUS E 28 7 8 9
10 POWER 0 4 8 29 11 12 13
OTHER STATUS NA 30 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT RELEASED OF RELEASE 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED DESCRIPTION 45 46 47 48 49 50

21 NAME OF PREPARER R.D. Binz IV
22 NRC USE ONLY
23 PHONE 609-971-4898
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50