



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 455-5901

February 22, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58 and DPR-74
Docket No. 50-315 and 50-316

Dear Mr. Keppler:

On February 17, 1983, we submitted a Licensee Event Report that was incorrectly numbered. This report should have been submitted as Unit 1 LER 83-001/03L-0 (previously submitted as Unit 2 LER 83-022/03L-0). An amended copy of the Licensee Event Report is attached which reflects the correct number. Would you please have this Licensee Event Report distributed to all concerned parties.

I am sorry for any inconvenience this may have caused you.

Sincerely,


W.G. Smith, Jr.
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
M.P. Alexich
R.F. Kroeger
B. Germano
E.R. Swanson/N.E. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

FEB 24 1983

IE22