

**LICENSEE EVENT REPORT**

Attachment to AECM-83/0120

Page 1 of 1

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	4	1	6	7	0	1	1	8	8	3	8	0	2	2	3	8	3	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 18, 1983, the supervision system for fire rated door 1A211 in the

0 3 | Auxiliary Building and fire rated doors OC103, OC410, and OC706 in the Control

0 4 | Building alarmed with the doors closed. The doors were declared inoperable and fire

0 5 | watches were established in accordance with T.S.3.7.7. The event had no effect on

0 6 | health and safety of the public and did not constitute a threat to plant safety. This

0 7 | is submitted as a Special Report in accordance with T.S.3.7.7.

0	8		80
7	8	9	

SYSTEM CODE A B		CAUSE CODE E		CAUSE SUBCODE B		COMPONENT CODE I N S T R U						COMP. SUBCODE S		VALVE SUBCODE Z	
EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 3 3		OCCURRENCE CODE 9 9		REPORT TYPE X		REVISION NO. 0							
ACTION TAKEN E		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER P 3 0 2	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was due to limit and magnetic switches being out of adjustment. Door OC410,  
1 1 however, was found operable when maintenance personnel investigated. Switches were  
1 2 adjusted, the supervision system was functionally checked, and all doors were  
1 3 restored to operability by January 31, 1983. This is submitted as a final report.

1 4 \_\_\_\_\_

1 5 FACILITY STATUS (28) % POWER 0 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) A Alarmed Condition DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 7 8 9 Z 33 10 Z 34 11 NA 44  
LOCATION OF RELEASE (36)  
45 NA 80

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION (39)					
1	7	0	0	0	(37)	Z	(38)	NA	

7	8	9	11	12	13	80
			PERSONNEL INJURIES			
			NUMBER	DESCRIPTION	(41)	

1	8		0	0	0	(40)							NA													
7	8	9		11	12													8303010201 830223								
LOSS OF OR DAMAGE TO FACILITY						(43)													PDR ADOCK 05000416							
TYPE DESCRIPTION																										

TYPE		DESCRIPTION		S		PDR	
1	9	Z	42	NA			

PUBLICITY  
ISSUED DESCRIPTION (45) NA NRC USE ONLY

NAME OF PREPARER Ron Byrd and Boyd Shingleton

PHONE