

CONTROL BLOCK: 1 6 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1

M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 1 2 8 8 3 8 0 2 2 4 8 3 9

DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2

On January 28, 1983, fire doors 1A401, 1A202, and 1A108 (Auxiliary Building) were

0 3

blocked open to allow the routing of electrical cords and air hoses for planned

0 4

maintenance activities conducted in the areas secured by these fire doors. This

0 5

required operating under the action statements of T.S.3.7.7. The event had no effect

0 6

on the health and safety of the public and did not constitute a threat to plant

0 7

safety. This is reported pursuant to T.S.6.9.1.13.b.

0 8

0 9

A B 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 18 COMP. SUBCODE 19 VALVE SUBCODE 20

17

LER/RO REPORT NUMBER 8 3 0 2 9 0 3 L 0

EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 26 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0

The doors were blocked open to perform planned maintenance. An hourly fire watch

1 1

was conducted in accordance with T.S.3.7.7.a. The subject fire doors were locked

1 2

and the alarms activated within 7 days. This is a final report.

1 3

1 4

1 5

G 28 0 0 0 29 NA A 31 Planned Maintenance

FACILITY STATUS 7 8 9 % POWER 10 12 OTHER STATUS 13 30 METHOD OF DISCOVERY 45 46 DISCOVERY DESCRIPTION 32

1 6

Z 33 Z 34 NA NA

ACTIVITY CONTENT 7 8 9 RELEASED OF RELEASE 10 11 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 7

0 0 0 37 Z 38 NA

PERSONNEL EXPOSURES 7 8 9 NUMBER 11 TYPE 12 DESCRIPTION 39

1 8

0 0 0 40 NA

PERSONNEL INJURIES 7 8 9 NUMBER 11 DESCRIPTION 41

1 9

Z 42 NA

LOSS OF OR DAMAGE TO FACILITY 7 8 9 TYPE 10 DESCRIPTION 43

2 0

N 44

PUBLICITY 7 8 9 ISSUED 10 DESCRIPTION 45

8303010233 830224
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton PHONE

GPO 817-926