

**Detroit
Edison**

Donald A. Wells
Manager Quality Assurance
(313) 237-9657

2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

February 10, 1983
EF2-61534

Mr. James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Report of 10CFR50.55(e) Item on Questionable Quality Control
Acceptance of Pipe Hanger Installations (#82)


Dear Mr. Keppler:

The report sent to you recently on the above subject, EF2-61526, dated January 14, 1983, was erroneously identified as a final report. We wish to amend it to an interim report on the subject.

A final report will be issued when the actions outlined in the Confirmatory Action Letter of December 10, 1982, have been completed. It is expected that the work of implementing the agreed-upon actions will be completed by June 1, 1983. The final report on this 50.55(e) item should be issued by June 30, 1983.

If you have any questions concerning this matter, please contact Mr. T.A. Alessi, Director - Project Quality Assurance.

Very truly yours,



DAW/TAA/pn

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Senior Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166

8303010631 830210
PDR ADOCK 05000341
S PDR

54-241

IE27

FEB 23 1983