



**Commonwealth Edison**  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marseilles, Illinois 61341  
Telephone 815/357-6761

50-373

February 18, 1983

James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Sir:

In accordance with LaSalle County Station Unit 1 Facility Operating License NPF-11, Appendix B, Section 3.2, we are submitting to you a copy of the NPDES noncompliances for LaSalle County Nuclear Generating Station Permit No. 1L0048151.

G. J. Diederich  
Superintendent  
LaSalle County Station

GJD/FRL/JDW/rg

Enclosure

cc: DVR Report

8303080066 830218  
PDR ADOCK 05000373  
S PDR

FEB 23 1983

IE22



Commonwealth Edison  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marseilles, Illinois 61341  
Telephone 315/357-6761

January 31, 1983

U.S. Environmental Protection Agency  
Region V, Enforcement Division  
ATTN: Chief, Compliance Unit  
230 South Dearborn Street  
Chicago, IL 60604

Illinois Environmental Protection Agency  
Division of Water Pollution Control  
Compliance Management Unit  
2200 Churchill Road  
Springfield, IL 62706

Dear Sir:

Subject: NPDES Noncompliances for LaSalle County Nuclear  
Generating Station Permit No. IL0048151

In accordance with Standard Condition 12, we wish to submit the following notice of noncompliances, which are listed chronologically in the attached table.

If there are any questions, please contact Joe Williams of my staff at (815) 357-6761, extension 201.

G. J. Diederich  
Station Superintendent

~~FRL~~ SKD  
GJD/FRL/JDW/msj

cc: Director of Water Quality, Environmental Affairs  
Manager, Nuclear Stations Division

LASALLE COUNTY NUCLEAR GENERATING STATION  
N.P.D.E.S. PERMIT NO: IL0048151  
NONCOMPLIANCE REPORT

DISCHARGE NUMBER AND DESCRIPTION: 001c Low Volume Waste  
Regen. Wastes Soln. Discharge Tank

PARAMETER AND PERMIT LIMIT: Total suspended solids, 15 mg/l  
Total Iron, 1.0 mg/l

NONCOMPLIANCE, DATE, AND DURATION:  
TSS 67 mg/l, 26JAN83, 3 hours  
Total iron 1.9 mg/l, 26JAN83, 3 hours

CAUSE OF NONCOMPLIANCE:

The most probable cause of these noncompliances is the addition to the tank of construction wastes from the Unit 2 condensate polishing system.

CORRECTIVE ACTION:

A modification has been initiated to provide the option for treatment of these tanks in the wastewater treatment facility. The modification should be implemented by February 1983.

DATE RECOGNIZED AS A VIOLATION:

28JAN83

DATE INVESTIGATED:

28JAN83