

# Illinois Power Company

U-0603

L08-83(01-15)L

500 SOUTH 27TH STREET, P. O. BOX 511, DECATUR, ILLINOIS 62525-1805

Docket Number 50-461

February 15, 1983

Mr. James G. Keppler  
Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Reference: IE Bulletin No. 82-04 dated December 3, 1982

Subject: Clinton Power Station Unit 1


Dear Mr. Keppler:

This is in response to the referenced IE bulletin on the subject of deficiencies in primary containment electrical penetration assemblies.

No Bunker Ramo Company electrical penetrations which use the hard epoxy module design are installed or planned to be installed in safety-related systems at the Clinton Power Station.

I hereby affirm that the information in this letter is correct to the best of my knowledge.

Sincerely,



G. E. Wuller  
Supervisor-Licensing  
Nuclear Station Engineering

GEW/jmm

cc: H. H. Livermore, NRC Resident Inspector  
H. Abelson, NRC Clinton Project Manager  
Director, Office of I & E, USNRC, Wash. D.C.  
Illinois Department of Nuclear Safety

IE11