

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	CAT		50

REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 2 0 5 8 3 8 0 3 0 3 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Unit 1 in mode 1 (100% power) at 0115 CST on 02/05/83, the ice condenser temperature

03 | monitoring system recorder in the main control room was determined inoperable. This

04 was discovered by an assistant unit operator (AUO) during required shift readings.

05 | This required entry into action statement (a) of LCO 3.6.5.2. There was no effect

06 upon public health and safety. Previous occurrences - none.

07 _____

018 | _____
7 . . 8 9

SYSTEM CODE 0 9		CAUSE CODE I F		CAUSE SUBCODE E		COMPONENT CODE I N S T R U						COMP. SUBCODE R		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 1 6		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN A		FUTURE ACTION Z	
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER W 1 3 0			
33		34		35		36		37		38		39			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)															

10 The print head assembly on this Westronics, Inc., Model M11-D2 recorder failed

11 | upscale. The cause is unknown. The recorder could not be repaired. A new type

1 2 recorder (Westronics Model M11-E). was installed and the ice condenser temperature

13 monitoring system was returned to service at 1648 CST on 02/08/83. No additional

1.4 corrective actions are planned.

FACILITY STATUS (1) 5 (2) E (3) 28 (4) 1 (5) 0 (6) 0 (7) 29 (8) NA (9) 30
 % POWER (10) 1 (11) 0 (12) 0 (13) 29 (14) NA (15) 30
 OTHER STATUS (16) NA (17) 30
 METHOD OF DISCOVERY (18) B (19) 31 (20) Operator observation (21) 72
 DISCOVERY DESCRIPTION (22) 72
 ACTIVITY CONTENT (23) 1 (24) 6 (25) Z (26) 33 (27) Z (28) 34 (29) NA (30) 35
 RELEASED OF RELEASE (31) NA (32) 35
 AMOUNT OF ACTIVITY (33) 35
 LOCATION OF RELEASE (34) 36
 PERSONNEL EXPOSURES (35) 1 (36) 7 (37) 0 (38) 0 (39) 0 (40) Z (41) 38 (42) NA (43) 39
 NUMBER (44) 0 (45) 0 (46) 0 (47) Z (48) 38 (49) NA (50) 39
 TYPE (51) 39
 DESCRIPTION (52) 39
 PERSONNEL INJURIES (53) 1 (54) 8 (55) 0 (56) 0 (57) 0 (58) 40 (59) NA (60) 41
 NUMBER (61) 0 (62) 0 (63) 0 (64) 40 (65) NA (66) 41
 DESCRIPTION (67) 41
 LOSS OF OR DAMAGE TO FACILITY (68) 1 (69) 9 (70) Z (71) 42 (72) NA (73) 43
 TYPE (74) Z (75) 42 (76) NA (77) 43
 DESCRIPTION (78) 43
 PUBLICITY (79) 2 (80) 0 (81) N (82) 44 (83) NA (84) 45
 ISSUED (85) N (86) 44 (87) NA (88) 45
 DESCRIPTION (89) 45
 8303140501 830303
 PDR ADOCK 05000327
 S PDR
 NRC USE ONLY

Name of Preparer: D. A. Kulisek /M. R. Harding

Phone: (615) 751-0349