

**Florida
Power**
CORPORATION

March 4, 1983
#3F-0383-05

Mr. J. P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
101 Marietta Street, Suite 2900
Atlanta, GA 30303

SUBJECT: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
IE Bulletin No. 83-01:
Failure of Reactor Trip Breakers (Westinghouse DB-50)
to Open on Trip Signal

Dear Mr. O'Reilly:

Florida Power Corporation does not currently use Westinghouse DB-50 breakers with the subject undervoltage trip attachment in safety related systems. Future potential use of these breakers will be subject to appropriate procurement controls.

Sincerely,

G. R. Westafer
Manager
Nuclear Licensing and Fuel Management

PGH/caw

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


8303110234 830304
PDR ADDCK 05000302
Q PDR

IE11


STATE OF FLORIDA

COUNTY OF PINELLAS

G. R. Westafer states that he is the Manager, Nuclear Licensing and Fuel Management, of Florida Power Corporation; that he is authorized on the part of said company to sign and file with the Nuclear Regulatory Commission the information attached hereto; and that all such statements made and matters set forth therein are true and correct to the best of his knowledge, information, and belief.


G. R. Westafer

Subscribed and sworn to before me, a Notary Public in and for the State and County above named, this 4th day of March, 1983.


Notary Public

Notary Public, State of Florida at Large,
My Commission Expires: November 19, 1986

NOTARY PUBLIC STATE OF FLORIDA
MY COMMISSION EXPIRES NOV 19 1986
BONDED THRU GENERAL INSURANCE UND