



March 1, 1983

Log No. K83-405
File: RR2 (NP-33-83-14)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 83-007
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: January 31, 1983

Enclosed are three copies of Licensee Event Report 83-007 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8303140528 830301
PDR ADOCK 05000346
S PDR

MAR 7 1983

IE22