

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

February 25, 1983

RECEIVED  
NRC

1983 MAR -1 PM 12:14

SCE

REGION V

TELEPHONE  
(714) 492-7700

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361 and 50-362  
14-Day Follow-Up Report  
Licensee Event Report No. 83-010 (Docket No. 50-361)  
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter H.B. Ray (SCE) to R.H. Engelken (NRC)  
dated February 14, 1983

The referenced letter provided you with confirmation of our prompt notification, pursuant to Section 6.9.1.12.b of Appendix A, Technical Specifications to Operating Licenses NPF-10 and NPF-15 for San Onofre, Units 2 and 3, involving the Control Room Emergency Air Cleanup System (CREACUS).

Pursuant to Section 6.9.1.12.b, this submittal provides the required 14-day follow-up report and a copy of Licensee Event Report (LER). Since the occurrence involves a shared system between Units 2 and 3, in accordance with NUREG-0161, a single LER 83-010 for Unit 2 (Docket No. 50-361) is provided to address this event.

If there are any questions regarding this event, please contact me.

Sincerely,

*HB Ray / JRM*

Enclosure: LER 83-010

8303110267 830225  
PDR ADOCK 05000361  
S PDR

IE-22  
83-88

February 25, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)

R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)