

TENNESSEE VALLEY AUTHORITY  
CHATTANOOGA, TENNESSEE 37401  
1750 Chestnut Street Tower II

83 MAR 7 All : 27

March 3, 1983

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/83021

The enclosed report provides details concerning the failure of one  
channel of heat tracing of the 4-inch line to the boron injection  
tank (BIT) and the BIT outlet 1-inch relief line to the holdup tank.  
This report is submitted in accordance with Sequoyah unit 1 Technical  
Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
H. J. Green  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

8303140548 830303  
PDR ADOCK 05000327  
S PDR

OFFICIAL COPY

IE 22

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer