

LICENSEE EVENT REPORT

Attachment to AECM-83/0143

Page 1 of 1

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 4 1 6 7 0 2 0 1 8 3 8 0 3 0 3 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On February 1, 1983, fire door 1A307 to the RHR 'B' Heat Exchanger Room, was blocked open to allow routing of a hose for a planned maintenance activity. In accordance with T.S.3.7.7, a fire watch was established within 1 hour. The event had no effect on the health and safety of the public and did not constitute a threat to plant safety. This is reported pursuant to T.S.6.9.2.

SYSTEM CODE 0 9		CAUSE CODE A B		CAUSE SUBCODE Z		COMPONENT CODE Z Z Z Z Z Z						COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 4 5		OCCURRENCE CODE 9 9		REPORT TYPE X		REVISION NO. 0					
ACTION TAKEN X		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The fire door was returned to its normally closed position and the alarm circuits
1 1 | were activated on February 23, 1983, at 0430 hours. The LCO was closed on the
1 2 | same date. The required time to complete the work exceeded the time limit in
1 3 | T.S.3.7.7, therefore, this is being submitted as a Special Report. This is a final
1 4 | report.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	28	0	0	0	29	NA	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40			NA	41
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42			NA			43
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44			8303140565 830303 PDR ADOCK 05000416 S PDR			45
								NRC USE ONLY	

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton PHONE