

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

February 23, 1983

RECEIVED
NRC

1983 FEB 28 PM 1:27

SCE

REGION V

TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-018
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre, Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report for an occurrence involving Limiting Condition for Operation (LCO) 3.7.1.2 associated with the Auxiliary Feedwater (AFW) system. Enclosed LER 83-018 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,

H.B. Ray / NRC

Enclosure: LER 83-018

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

8303110347 830223
PDR ADOCK 05000362
S PDR

IE-22
83-84