

LICENSEE EVENT REPORT

Attachment to AECM-83/0142

Page 1 of 1

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 1 0 5 8 2 8 0 3 0 3 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During shutdown, fire door 1A106 (Auxiliary Building North stairwell door, elevation
03 93 feet) was opened in order to drain SSW Loop B. The fire door was opened to allow
04 passage of a hose to channel water from the flush and drain of SSW Loop B. An LCO
05 was entered in accordance with T.S.3.7.7. The event had no effect on the health
06 and safety of the public and did not constitute a threat to plant safety. This is
07 a Special Report submitted pursuant to T.S.3.7.7.a.

08
7 8 9
09
7 8 9
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16
9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 2 1 2 0 9 9 X 1
21 22 23 24 25 26 27 28 29 30 31 32
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 An hourly fire watch was established in accordance with T.S.3.7.7. The fire door
11 was opened to allow passage of a hose to channel water from the flush and drain of
12 SSW Loop B. The door was restored on December 29, 1982, upon completion of the
13 flush. This is a final report.

14
7 8 9
15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
B 28 0 0 0 29 NA A 31 Planned Action
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
20 PUBLICITY ISSUED DESCRIPTION 45
Z 44
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
8303140404 830302
PDR ADOCK 05000416
S PDR

NAME OF PREPARED R. W. Byrd and E. B. Shingleton

PHONE

NRC USE ONLY