



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

DMB

May 10, 1983

50-373
374

Mr. James G. Keppler
Regional Administrator
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Sir:

This Special Report is submitted in accordance with LaSalle Unit 1 Operating License NPF-11, Appendix B, Technical Specification 3.3.7.9 and 6.6.c.

On July 15, 1982, the ultraviolet fire detectors for Unit 1 and Unit 2 Refuel floor were taken out of service and a Special Report from R. H. Holyoak to James G. Keppler, dated August 10, 1982, was submitted in accordance with the action statement of Technical Specification 3.3.7.9.

As stated in the report, the U-V fire detectors were to be inoperable until completion of welding in Unit 2 containment (approximately nine months from the date of report).

As a result of continued Unit 2 construction work, the U-V fire detectors will be out of service until Unit 2 fuel load, which is currently scheduled for the fall of 1983.

At this time, the Unit 1 and Unit 2 refuel floors are not considered as part of the Unit 1 secondary containment as defined in the LaSalle County Station FSAR, Appendix N.

G.J. Diederich
Superintendent
LaSalle County Station

GJD/JK/sjc

8305240007 830510
PDR ADDCK 05000373
S PDR

MAY 19 1983

IF01