

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

ATLANTA, GEORGIA

1750 Chestnut Street Tower II

82 FEB 19 P 2: 11

February 17, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/81069 - REVISION 1

The enclosed report is a supplement to my letter dated December 11, 1981,
concerning the gaseous channel of continuous air monitor O-RM-90-252 which
read downscale during an internal calibration check of the counting
ratemeter. This report is submitted in accordance with Browns Ferry unit 1
Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8203080480 820217
PDR ADOCK 05000259
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 22 511