

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

May 18, 1983

TELEPHONE  
(704) 373-4831


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station, Unit 2  
Docket No. 50-370

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-370/83-08 was to have been submitted by May 18, 1983. This 30 day reportable occurrence (pursuant to T.S. 6.9.1.11) concerns T.S. 3.6.1.3, "Each containment air lock shall be operable...", which was violated on April 18, 1983. At this time, investigation of the incident and preparation of a report are not yet complete. The complete report will now be submitted by June 3, 1983.

Very truly yours,



Hal B. Tucker

PBN:jfw

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8305250525 830518  
PDR ADDCK 05000370  
S PDR

OFFICIAL COPY

IE 27