




**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET  
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 20, 1983

W3I83-0181  
Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 55  
"Hold Up and Boric Acid Make Up Tanks  
Incorrect Structural Calculations"  
Sixth Interim Report

REFERENCE: LP&L letter W3I83-0101 dated March 28, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 23, 1983.

At the present time, corrective action is scheduled for completion by May 31, 1983. Therefore, a Final Report will be delayed until June 21, 1983.

Very truly yours,

F. J. Drummond  
Project Support Manager - Nuclear

FJD/MAL:keh

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 3) Mr. E. L. Blake
- 4) Mr. W. M. Stevenson

8305270147 830520  
PDR ADOCK 05000382  
S PDR

IE275