




**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 20, 1983

W3I83-0182  
Q-3-A35.07.77

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 77  
"Inadequate Containment Purge Valves  
Closure Time and Flow Rate"  
Second Interim Report

REFERENCE: LP&L letter W3I83-0129 dated April 20, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 20, 1983.

At the present time, all hardware corrective action is complete and the supporting documentation is currently being reviewed for the Final Report. Therefore, a Final Report will be submitted by June 30, 1983.

Very truly yours,

F. J. Drummond  
Project Support Manager - Nuclear

FJD/MAL:keh

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

4) Mr. W. M. Stevenson