

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 2 2 0 0 1 0 0 0 0 0 1 0 0 3 4 1 1 1 1 1 4 5

CON'T 01 L 6 0 5 0 0 0 3 1 6 7 0 4 2 5 8 3 8 0 5 2 0 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 DURING NORMAL OPERATION, A REVIEW OF THE TRAIN A AND B LOWER CONTAINMENT AIRBORNE MONI-
03 TORS (ERS-2300 AND ERS-2400) REVEALED THAT THE MONITORS WERE NOT WIRED PER APPROVED
04 PHYSICAL PRINTS. ERS-2300 AND ERS-2400 WERE REMOVED FROM SERVICE TO MAKE CORRECTIONS.
05 THE REMOVAL OF THE MONITORS FROM SERVICE WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL
06 SPECIFICATION 3.3.2.1 TABLE 3.3-3 ITEM 3.c.2. THE ACTION STATEMENT WAS MET AND THE
07 PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. SIMILAR OCCURRENCES INCLUDE: 050-315/83-
 38.

SYSTEM CODE B A 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16
 LER/RO REPORT NUMBER 8 3 17 EVENT YEAR 8 3 21 22 SEQUENTIAL REPORT NO. 0 4 3 24 26 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32
 ACTION TAKEN F 13 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER E 0 7 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
00 INVESTIGATION REVEALED THAT THE MONITORS WERE NOT WIRED PER APPROVED PHYSICAL PRINTS.
01 THE MONITORS WERE REMOVED FROM SERVICE, CORRECTIONS WERE MADE AND THE MONITORS WERE
02 RETURNED TO SERVICE. NO FURTHER ACTION IS PLANNED.

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION TECHNICIAN OBSERVATION 32
 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NAME OF PREPARER R. A. PALMER 68 69 PHONE 616-465-5901 80 81