

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 20, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-48. This report concerns T.S.3.4.5, "All power operated relief valves (PORVs) and their associated block valves shall be operable", and T.S.3.3.3.6, "The accident monitoring instrumentation channels shown in Table 3.3-10 shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Although my letter of July 6, 1982 stated that this report would be submitted by July 16, it is being submitted 2 working days later. We regret any inconvenience this delay may have caused.

Very truly yours,


William O. Parker, Jr.

PBN/jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

02 JUL 26 4 8:30
USNRC REGION II
ATLANTA, GEORGIA
[OFFICIAL COPY]

8208020087 820720
PDR ADOCK 05000369
S PDR

TE 22