

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 20, 1982

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-55 was to have been submitted by July 20, 1982. This 30 day reportable occurrence (pursuant to T.S.6.9.1.13) concerns T.S. 3.3.3.6, "The accident monitoring instrumentation channels shown in Table 3.3-10 shall be operable", which was violated on June 20, 1982. At this time, investigation of the incident and preparation of a report are not yet completed. The report will now be submitted by July 29, 1982.

Very truly yours,



William O. Parker, Jr.

PBN/jfw

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

Mr. P. R. Bemis  
Senior Resident Inspector-NRC  
McGuire Nuclear Station

32 JUL 26 4 8 : 38

USNRC REGION 2  
ATLANTA, GEORGIA

OFFICIAL COPY

8208020144 820720  
PDR ADOCK 05000369  
S PDR

1022