

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 22, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Nuclear Station
Docket No. 50-269

Dear Mr. O'Reilly:

On June 22, 1982 the NRC Resident Inspector was informed that Keowee Hydro Unit 1 was declared inoperable due to the main Tie Breaker to the Overhead Transmission Path (ACB-1) not closing.

Reportable Occurrence Report RO-269/82-11 providing details of this incident was to have been submitted to you by July 22, 1982, pursuant to Technical Specification 6.6.2.1.b(2). However, the investigation of this incident and the preparation of a report are incomplete at this time. It is expected that the investigation and report will be completed, reviewed, and submitted to you no later than August 20, 1982.

Very truly yours,



William O. Parker, Jr.

JFK/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

Mr. Philip C. Wagner
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555