

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

CON'TREPORT
SOURCE

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On August 14, 1982, with the reactor operating at power, emergency feedwater supply to the Loop 1 helium circulator pelton wheel drives was isolated for 5.25 hours to perform maintenance to a pressure control valve, PV-21243-1. This is a degraded mode of LCO 4.2.2, Section a, of the Fort St. Vrain Technical Specifications and is being reported per AC 7.5.2(b)2. Similar RO's: 82-031, 82-028, 82-015, 81-060, and 81-054. No affect on public health or safety.

08																				80		
7	8	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE					
09			H	H	(11)	E	(12)	B	(13)	V	A	L	L	V	E	X	(14)	F	(15)	H	(16)	
7	8		9	10	11	12	13	14	15	16	17	18	19	20								
			EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.											
(17)	LER RO REPORT NUMBER		8	2	(22)	034		03		0		0										
			21	22	23	24	25	26	27	28	29	30	31	32								
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
A	(18)	Z	(19)	Z	(20)	Z	(21)	0	0	0	0	Y	(23)	N	(24)	N	(25)	M	1	2	0	(26)
13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Normal wear caused internal and outlet piping leakage on PV-21243-1, a Masoneillan,
1 1 | model 9460, Serial 81026-9-1, carbon steel, air operated diaphragm valve. The in-
1 2 | ternals were replaced/repared, and the outlet piping was replaced with thicker
1 3 | walled pipe. The header was returned to service. No further corrective action is
1 4 | anticipated or required.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (2) F (28) % POWER (10) 0 (11) 7 (12) 0 (29) OTHER STATUS (30) N/A METHOD OF DISCOVERY (31) A DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT (1) 6 (2) Z (33) RELEASED OF RELEASE (10) 1 (11) 2 (34) AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	0101	Z	N/A

PERSONNEL INJURIES										
NUMBER					DESCRIPTION					
1	8	0	0	0	40	N/A				

8208270128 820812

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

1 9 7 8 9 10

Z (42) N/A

8207270127 820713
PDR AD0CK 05000267
S PDR

PUBLICATIONS
ISSUED (20) DESCRIPTION (45) N/A (45) NRC USE ONLY

NAME OF PREPARER

PHONE: (303) 785-2224