

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

May 27, 1983

83 MAY 31
ALL: 23
USNRC REGION 1
ATLANTA, GEORGIA

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303

SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Special Report per
Technical Specification 6.9.2

Dear Mr. O'Reilly:

This Special Report is being submitted as a followup to a Special Report dated April 15, 1983, regarding entry into the Action Statement of Technical Specification 3.7.10, "Fire Rated Assemblies," on March 17, 1983. As stated in this initial report, Virgil C. Summer Nuclear Station began a plant outage to perform the required D-3 Steam Generator modifications. In conjunction with this, a number of other modifications were undertaken, some of which required the removal from service of certain fire barriers.

Attached is a listing by room number of the areas affected during various modifications that were out of service longer than the specified seven (7) days. Also listed is the completion date for each area. Restoration to service of the affected fire rated assemblies was accomplished through an inspection performed by the Quality Control group on site.


During the time the fire rated assemblies were out of service, a one (1) hour fire watch patrol was in effect for these areas pursuant with the requirements of Technical Specification 3.7.10, Action Statement (a).

Virgil C. Summer Nuclear Station entered Mode 4 on May 17, 1983, and as stated in our initial report, we are submitting this report to the Nuclear Regulatory Commission within ten (10) days following the entry into Mode 4.

Mr. James P. O'Reilly
Special Report
Page Two
May 27, 1983

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/dwf
Attachment

cc: V. C. Summer
E. H. Crews, Jr.
T. C. Nichols, Jr., /O. W. Dixon, Jr.
E. C. Roberts
H. N. Cyrus
Group/General Managers
O. S. Bradham
R. B. Clary
C. A. Price
A. R. Koon
D. A. Lavigne
C. L. Ligon (NSRC
G. J. Braddick
J. C. Miller
J. L. Skolds
J. B. Knotts, Jr.
I&E (Washington)
Document Management Branch
INPO Records Center
NPCF
File (Lic./Eng.)

ATTACHMENT

<u>BUILDING</u>	<u>ROOM</u>	<u>DATES OF INOPERABILITY</u>
CONTROL	12-03	4/16--5/06
	12-04	4/16--5/13
	25-01	3/19--5/05
	25-02	4/14--5/05
	36-03	4/14--4/28
	36-04	4/08--5/05
	36-09	3/19--4/16
	48-01	4/29--5/03
	48-02	4/04--4/11, 4/16--4/30
	63-05	3/30--5/03, 5/04--5/11
AUXILIARY	12-02	4/21--5/12
	26-01	4/16--4/25
	36-18	4/16--4/25, 4/28--5/03
	63-01	3/23--4/19
INTERMEDIATE	12-02	3/22--4/30
	36-02	4/07--5/03
FUEL HANDLING	36-01W	4/06--4/16
WEST PENETRATION ACCESS AREA	12-01	3/31--5/10
	36-01	3/11--5/11
EAST PENETRATION ACCESS AREA	12-02	3/23--5/06
	36-02	3/11--5/09
DIESEL GENERATOR	436'	4/21--4/27