



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

October 4, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Fire Door Inoperability
Reference: LER 82-069/03 L-0
AECM-82/436

On September 3, 1982, the supervisory alarm on the fire door separating the RHR "A" piping room and its east passageway went into alarm and would not clear. The continuous alarm was caused by a door microswitch which was out of adjustment. A Limiting Condition for Operation was entered pursuant to T.S.3.7.7. Attached is LER 82-069/03 L-0.

Yours truly,

J. P. McGaughy
for J. P. McGaughy

JPM:lm
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Document Control Desk (w/a)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8210080277 821004
PDR ADOCK 05000416
S PDR

AEIN1

Member Middle South Utilities System

OFFICIAL COPY

LE22