

EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: (704) 373-7432

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

May 26, 1983


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-24. This report concerns T.S. 3.7.11, "...All sealing devices in fire rated assembly penetrations (fire doors, fire windows, fire dampers, cable piping, and ventilation duct penetration seals) shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

PBN:jfw  
Attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

83 JUN 6 9:23  
USNRC REGION I  
ATLANTA, GEORGIA

OFFICIAL COPY

IE 22  
111