


TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER DALLAS, TEXAS 75201-3050

R. J. GARY  
EXECUTIVE VICE PRESIDENT  
AND GENERAL MANAGER



February 28, 1983  
TXX-3634

Mr. G. L. Madsen, Chief  
Reactor Project Branch 1  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

Docket Nos.: 50-445  
50-446

COMANCHE PEAK STEAM ELECTRIC STATION  
PACIFIC PUMP MULTI-VANE DIFFUSER LINEAR INDICATIONS  
QA FILE: CP-82-04, SDAR-74  
FILE NO.: 10110

IE-27

Dear Mr. Madsen:

On April 14, 1982, we verbally informed your Mr. R. G. Taylor of a deficiency regarding Pacific Pump multi-vane diffuser cracking. We have submitted interim letters TXX-3518, TXX-3563, TXX-3576, TXX-3593, and TXX-3609 dated May 14, 1982, August 25, 1982, October 1, 1982, December 7, 1982 and January 13, 1983 respectively.

We have completed our investigation and concluded that the matter is not reportable under 10 CFR 50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours,

*R. J. Gary*

RJG:aq

cc: NRC Region IV- (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

8303080378 830228  
PDR ADOCK 05000445  
S PDR