



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-3843

April 24, 1981

RBG - 10,176
File Code G9.5
G9.25.1.1

Mr. K.V. Seyfrit, Director
U.S. Nuclear Regulatory Commission
Region IV, Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Seyfrit:

River Bend Station - Unit 1
Docket No. 50-458

The investigation of the incident and assessment of the damage to the Primary Shield Wall as reported in our February 24, 1981 letter, has not been completed. Our investigation is anticipated to be complete by June 15, 1981. At that time, a final report will be filed with your office concerning this reportable 10CFR50.55(e).

Sincerely,

E L Draper, Jr.

E.L. Draper, Jr.
Vice President - Nuclear Technology

ELD/RJK/cb

cc: Director of Inspection and Enforcement, U. S. Nuclear
Regulatory Commission, Washington, D.C. 20555

III C

1E27

8303080405 810424
PDR ADOCK 05000458
S PDR