


INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

June 3, 1983

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm my verbal report to your Mr. E.R. Swanson at 0845 hours on June 3, 1983. At this time I informed Mr. Swanson that during the conduct of an operational surveillance test both Containment Spray Systems were made inoperable for a time period of approximately 15 minutes. This error was discovered while performing an independent verification of the valve lineup. We immediately took the necessary action to restore the required Containment Spray System to an operable status.

As required by Technical Specification 6.9.1.12 a follow-up letter will be submitted within 14 days.

Sincerely,

E.L. Townley
E.L. Townley

Asst. Plant Manager

/jas

cc: J.E. Dolan
R.S. Hunter
M.P. Alexich
D. Wigginton, NRC
R.F. Kroeger
B. Germano
R.C. Callen MPSC
J.M. Hennigan
INPO

R.O. Bruggee EPRI
PNSRC
G. Charnoff, Esq.
E. Swanson/N. DuBry
J.F. Stietzel
W.G. Smith, Jr.
Dir., IE (40 copies)
Dir., MIPC (4 copies)

8306210074 830603
PDR ADOCK 05000316
S PDR

JUN 8 1983
IE22 11